




TS 1500

101827-07



GEZE




A


B




$a \leq 1100 \text{ mm}$






$a \leq 1100 \text{ mm}$









1





2



4x
5x52
4x
M5x42




4x
5x35
4x
M5x20




4x
M5x34

3




M5x42
5x52




M5x34
5x35

4



9 Nm M6x14.5





10 mm



9 Nm M6x14.5

10 mm


5

 $a = 950 - 1100 \text{ mm}$  $a < 950 \text{ mm}$  $a = 950 - 1100 \text{ mm}$  $a < 950 \text{ mm}$ 



6

2x
5x20





2x
M5x16





7













8



9



i

 $a \leq 1100 \text{ mm}$  $a \leq 1100 \text{ mm}$ 

GEZE GmbH

P.O.Box 1363

Reinhold-Vöster-Straße 21-29

71229 Leonberg

Germany

Tel.: 0049 7152 203-0

Fax: 0049 7152 203-310

www.geze.com

101827-07



GEZE